Suzanne Steab - April 2011 Inspection Reports

K

From:

Karl Houskeeper

To:

JohnGefferth@consolenergy.com; PeterBehling@consolenergy.com; SteveBe...

Date:

5/4/2011 3:18 PM

Subject:

April 2011 Inspection Reports

CC:

ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov

Attachments: Hidden Valley April 2011.pdf; Emery April 2011.pdf

Attached are the April 2011 inspection reports for Hidden Valley and Emery.

Thanks,

Karl



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Representativ	es Present During the Inspection:
Company	Peter Behling
OGM	Karl Houskeeper

Inspection Report

Permit Number:	C0150015				
Inspection Type:	PARTIAL				
Inspection Date:	Tuesday, April 19, 2011				
Start Date/Time:	4/19/2011 8:00:00 AM				
End Date/Time:	4/19/2011 1:30:00 PM				
Last Inspection:	Tuesday, March 22, 2011				

Inspector: Karl Houskeeper,

Weather: Clear/Windy, Temp. 48 Deg. F. InspectionID Report Number: 2718

> Accepted by: jhelfric 5/3/2011

Permitee: CONSOLIDATION COAL CO Operator: CONSOLIDATION COAL CO

Site: EMERY DEEP MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

442.50	Total Permitted
248.50	Total Disturbed
	Phase I
	Phase II
	Phase III

Types of Operations ✓ Federal ✓ Underground State Surface County Loadout **✓** Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl Houskeeper,

Inspector ID Number: 49

Harld. Harbeyon

Tuesday, Apri

Permit Number: C0150015 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 19, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 For PARTIAL inspections check only the elements evaluated.
 Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale		i		
2.	Signs and Markers	V		~	[]
3.	Topsoil				L/
4.a	Hydrologic Balance: Diversions	V	[]	~	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	Y			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations		O	C	
5.	Explosives		IJ		
6.	Disposal of Excess Spoil, Fills, Benches		(1)		Ĺ
7.	Coal Mine Waste, Refuse Piles, Impoundments	V			(7)
8.	Noncoal Waste	y	П	C)	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				tai
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	D	F		
13.	Revegetation	,i			
14.	Subsidence Control	irrett Tanad			
15.	Cessation of Operations			17)	
16.a	Roads: Construction, Maintenance, Surfacing		[]		
16.b	Roads: Drainage Controls	###*			
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	()			
19.	AVS Check		IJ		
20.	Air Quality Permit	[]	Ü		
21.	Bonding and Insurance				
22.	Other		[77]	F-1	[***]

Inspection Continuation Sheet

Permit Number: C0150015 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 19, 2011

Page 3 of 3

2. Signs and Markers

The mine identification signs were observed at he main facility and at the 4th East Portal Area. The signs contained the required information.

4.a Hydrologic Balance: Diversions

Some tumble weeds are collected around diversion inlets and outlets. The weeds should be removed to prevent plugging of the diversions.